

# Hydrogen Sulfide 0.2/a

Order No. 81 01 461

## Application Range

Standard Measuring Range:	0.2 to 5 ppm
Number of Strokes n:	10
Time for Measurement:	approx. 5 min
Standard Deviation:	± 5 to 10 %
Color Change:	white → pale brown

## Ambient Operating Conditions


Temperature:	10 to 30 °C
Absolute Humidity:	3 to 15 mg H <sub>2</sub> O / L

## Reaction Principle



## Cross Sensitivity

Sulfur dioxide and hydrochloric acid in the TLV range do not interfere.



*Northside Sales, Co.*

Safety & Industrial Products

800-467-9005

ST-192-2001